

# Standing Water - Not A Problem With Belzona

ID: 498

**Industry:** *General Industry*  
**Application:** *RPA-Roof Problem Areas*  
**Substrate:** *Stainless Steel*  
**Products:** *\* Belzona® 3111 (Flexible Membrane) ,*  
*\* Belzona® 3921 (GSC Surface Conditioner) ,*  
*\* Belzona® 9311 (Membrane Reinforcing Sheet) ,*

**Customer Location:** *Air Force Base, Texas - USA*  
**Application Date:** *March 2005*

## Problem

*Leaking gutters*



## Photograph Descriptions

- \* Gutters conditioned with Belzona® 3921 and seams coated with Belzona® 3111. ,
- \* Seams coated with Belzona® 3111. ,
- \* First coat of Belzona® 3111. ,
- \* Second coat of Belzona® 3111. ,

## Application Situation

Stainless steel gutters

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-7.

## Belzona Facts

Gutters on roof were coated with “low bid” product. Subsequent leaks soon appeared. Client wanted a more durable solution and chose Belzona once again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve