

BELZONA® Macht poröses Mauerwerk wetterfest

ID: 5084

Industrie: Gebäude & Strukturen
Anwendung: Wandproblembereiche
Substrat: Sandstein
Produkte: * Belzona® 5122 (Clear Cladding Concentrate),

Standort des Kunden: Privathaus, Manchester, England
Antragsdatum: August 2007

Problem

Das Haus wurde kürzlich renoviert und außen sandgestrahlt. Dieser Vorgang entfernte die Abdichtungseigenschaften des Mauerwerks, was ein Eindringen von Feuchtigkeit in das Haus zur Folge hatte.



Fotobeschreibungen

- * Ansicht der Immobilie ,
- * Abgeklebte Fenster und fertig zum Beschichten ,
- * Belzona® 5122 mit Spritzeinheit ,
- * Während der Anwendung ,

Anwendungssituation

Natursteinhaus

Anwendungsverfahren

Die Anwendung wurde gemäß dem Belzona Know-how System Infoblatt WPA-8 durchgeführt.

Belzona-Fakten

Der Kunde wollte einen natürlichen Anblick haben und keinerlei Glanz nachdem das Gebäude beschichtet ist. Zusätzlich sollte das

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

Material der Wahl auch mikroporös sein.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

