

# BELZONA® Macht poröses Mauerwerk wetterfest

ID: 5084

Industrie: Gebäude & Strukturen  
Anwendung: Wandproblembereiche  
Substrat: Sandstein  
Produkte: \* Belzona® 5122 (Clear Cladding Concentrate),

Standort des Kunden: Privathaus, Manchester, England  
Antragsdatum: August 2007

## Problem

Das Haus wurde kürzlich renoviert und außen sandgestrahlt. Dieser Vorgang entfernte die Abdichtungseigenschaften des Mauerwerks, was ein Eindringen von Feuchtigkeit in das Haus zur Folge hatte.



## Fotobeschreibungen

- \* Ansicht der Immobilie ,
- \* Abgeklebte Fenster und fertig zum Beschichten ,
- \* Belzona® 5122 mit Spritzeinheit ,
- \* Während der Anwendung ,

## Anwendungssituation

Natursteinhaus

## Anwendungsverfahren

Die Anwendung wurde gemäß dem Belzona Know-how System Infoblatt WPA-8 durchgeführt.

## Belzona-Fakten

Der Kunde wollte einen natürlichen Anblick haben und keinerlei Glanz nachdem das Gebäude beschichtet ist. Zusätzlich sollte das

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Material der Wahl auch mikroporös sein.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

[www.belzona.com](http://www.belzona.com)

