

# BELZONA REPAIRS CRUSHER'S ADJUSTMENT RING

ID: 5087

Industry: Mining & Quarrying

Customer Location: Mine, Chile

Application:

Application Date: February 2006

Substrate: Steel

Products: \* Belzona 1111 (Super Metal) ,  
\* Belzona 9411 (Release Agent) ,

## Problem

*The worn-out strip prevented the crusher from functioning well.*



## Photograph Descriptions

- \* Damage on the ring of the crusher ,
- \* Application of Belzona 9411 on the surface of the crusher ,
- \* Application of Belzona 1111 on the strip of the worn-out ring ,
- \* The ring repaired with Belzona 1111 ,

## Application Situation

Repair of the ring strip during an emergency stop.

## Application Method

First, the surface was prepared with emery cloth. Afterwards, Belzona 9411 was applied to the surface of the crusher in order to later apply Belzona 1111 to the worn-out ring and join the pieces together to mold Belzona 1111 between the two pieces.

## Belzona Facts

The mine did not have another ring to replace the damaged one and was not able to stop the operations. The application of Belzona 1111 and Belzona 9411 solved the problem and enabled the crusher to continue working until the new ring arrived.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve