

BELZONA WEATHERPROOFS TWO SUGAR SILOS

ID: 5175

Industry: *Food & Drink*
 Application: *WPA-Wall Problem Areas*
 Substrate: *Concrete*
 Products: ** Belzona 3111 (Flexible Membrane),*

Customer Location: *Sugar factory, Northern France*
 Application Date: *2014*

Problem

Infiltration of water into the tank through the porous concrete.



Photograph Descriptions

- * General view of the sugar plant ,
- * On-going application ,
- * Finished application ,
- * 6 years after the application ,

Application Situation

Two sugar silos within the sugar factory required weatherproofing

Application Method

Application was carried out in accordance with Belzona System Leaflet WPA-1. The work was completed by applying the system in vertical stripes of 6 meter width.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA[®]
 Repair • Protect • Improve

The Belzona 3111 system is proven to provide excellent long term weatherproofing of substrates. The application was carried out in 10 weeks with a team of 7 applicators. The silos have been revisited after 2 years and 6 years later, the application was still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

