

# BELZONA REPAIRS DAMAGED CLIP JOINT

ID: 5181


Industry: *General Industry*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*  
Application Date: *August 1996*

Substrate: *Mild steel and rubber.*  
Products: *\* Belzona 2311 (SR Elastomer) ,*

## Problem

*Clip joint had started to separate and tear.*



## Photograph Descriptions

- \* View of damaged clip joint ,
- \* Completed application. ,

## Application Situation

Clip joint tear.

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-4

## Belzona Facts

Using Belzona 2311 SR Elastomer allowed the belt to be repaired in place during a lunch break eliminating downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve