

# BELZONA REBUILDS SPLINE SHAFT

ID: 5182


Industry: *General Industry*  
Application: *MPT-Mechanical Power Transmission*

Customer Location: *BC, Canada*  
Application Date: *2005*

Substrate: *Steel*  
Products: *\* Belzona 1111 (Super Metal) ,*

## Problem

*Replacement part not readily available and purchasing the entire assembly would have been very costly.*



## Photograph Descriptions

- \* Preparation of the damaged areas in progress ,
- \* Splines reformed with Belzona 1111 ,
- \* Mounting flange in the process of being removed revealing rebuilt splines. ,

## Application Situation

Replacement part was not readily available.

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet MPT-5

## Belzona Facts

The use of Belzona allowed localized repairs to be executed with a minimal amount of downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve