

# BELZONA REPAIRS CABLE REINFORCED CONVEYOR BELT

ID: 5184


Industry: *General Industry*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*  
Application Date: *August 1996*

Substrate: *Rubber*  
Products: *\* Belzona 2311 (SR Elastomer) ,*

## Problem

*Cable stayed belt would develop cracks over a period of time.*



## Photograph Descriptions

- \* View of preparation in progress ,
- \* Close-up of one of the repair areas ,
- \* Completed application. ,

## Application Situation

Cracked cable stayed belt

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1

## Belzona Facts

Because of its rapid set-up time, coupled with its quick development of mechanical strength, Belzona 2311 allowed repairs to be made to the belt during unscheduled or short shut-downs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025