

BELZONA REBUILDS WORN CAT D9 SPLINESHAFT ASSEMBLY

ID: 5194

Industry: *Mining & Quarrying*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *BC, Canada*
Application Date: *N/A*

Substrate: *Steel*
Products: ** Belzona 1111 (Super Metal) ,*

Problem

The main drive spline on D-9 cat had worn loose over many years of service.



Photograph Descriptions

- * View of worn spline shaft assembly ,
- * Belzona 1111 Super Metal applied to worn splines ,
- * Components reassembled ,
- * The main framework that the Spline assembly is being bolted to ,

Application Situation

Worn spline shaft

Application Method

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet MPT-5

Belzona Facts

With applications of Belzona, the option to disassemble can be done when required

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve