

# BELZONA 1811 CERAMIC CARBIDE EXTENDS LIFE OF PUMP CASING

ID: 5198

Industry: Mining & Quarrying  
Application: CEP-Centrifugal Pumps  
Substrate: Stainless steel  
Products: \* Belzona 1811 (Ceramic Carbide) ,

Customer Location: BC, Canada  
Application Date: June 2000

## Problem

*Pumping drainage water from a gravel pit has a high percentage of entrained solids causing major erosion damage to pumps*



## Photograph Descriptions

- \* View of Pump ,
- \* Close-up of pump showing extent of erosion ,
- \* The internal surfaces of the pump casing are protected with Belzona 1811 ,

## Application Situation

Erosion on gravel slurry pump

## Application Method

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-1

## Belzona Facts

Coating the internal surfaces with a sacrificial coating such as Belzona 1811 ensures that the pump casing can be recycled many times over

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve