

BELZONA 2200 SERIES ELASTOMERS REPAIR SPLIT CONVEYOR BELT

ID: 5199


Industry: *Mining & Quarrying*
Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*
Application Date: *June 2000*

Substrate: *Rubber*
Products: ** Belzona 2211 (MP Hi-Build Elastomer) Belzona 2911 (QD Conditioner),*

Problem

A mechanical breakdown had caused the belt to be split over a length of approximately 100 feet.



Photograph Descriptions

- * Conveyor system in need of repair ,
- * The damaged portions of the belt were held together using mechanical fasteners ,
- * Close-up of fasteners and the prepared belt surfaces conditioned with Belzona 2911 ,
- * The completed repair ,

Application Situation

Split belt repair

Application Method

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1

Belzona Facts

The use of the two Belzona products allowed the plant to repair the damage in situ, saving many hours of downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve