

BELZONA ELASTOMERS USED TO PROTECT CONVEYOR BELT CLIPS

ID: 5200

Industry: *Mining & Quarrying*

Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*



Application Date: *1998*

Substrate: *Rubber and steel*

Products: ** Belzona 2211 (MP Hi-Build Elastomer) ,*

Problem

The fine gravel was constantly wearing out a clip joint



Photograph Descriptions

- * Preparation of the clip joint and damaged area in progress ,
- * Preparation completed ,
- * Area masked off and the prepared area conditioned with Belzona 2911 (QD Conditioner) ,
- * Completed application. ,

Application Situation

Belt clip

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1 and SHM-4

Belzona Facts

The use of the Belzona procedures enabled the clip joint to be permanently protected and the damaged section of the belt repaired at the same time

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024


BELZONA®
Repair • Protect • Improve