

# BELZONA ELASTOMERS USED TO PROTECT CONVEYOR BELT CLIPS

ID: 5200

Industry: *Mining & Quarrying*

Customer Location: *BC, Canada*

Application: *SHM-Solids Handling Machinery*


Application Date: *1998*

Substrate: *Rubber and steel*

Products: *\* Belzona 2211 (MP Hi-Build Elastomer) ,*

## Problem

*The fine gravel was constantly wearing out a clip joint*



## Photograph Descriptions

- \* Preparation of the clip joint and damaged area in progress ,
- \* Preparation completed ,
- \* Area masked off and the prepared area conditioned with Belzona 2911 (QD Conditioner) ,
- \* Completed application. ,

## Application Situation

Belt clip

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1 and SHM-4

## Belzona Facts

The use of the Belzona procedures enabled the clip joint to be permanently protected and the damaged section of the belt repaired at the same time

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve