BELZONA EXTENDS LIFE OF JET VALVE

ID: 5205

Industry: Mining & Quarrying Customer Location: BC, Canada
Application: CEP-Centrifugal Pumps Application Date: January 2004

Substrate: Cast Iron

Products: * Belzona 1311 (Ceramic R Metal),

* Belzona 1812 (Ceramic Carbide FP),

Problem

These jet valves would generally last about 5-6 months before they would wear through from the air / sand / water mixture pumped through them.









Photograph Descriptions

- * View of the volute area ,
- * Showing preparation in progress of the eroded area ,
- * Application of the Belzona material in progress ,
- * Application of the Belzona 1812 in progress,

Application Situation

Worn jet valves

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet CEP-1

Belzona Facts

These air valves cost approximately \$ 20,000.00 each. The Belzona repair cost less than 5% of the original cost and showed little signs of wearing out after a 9 month inspection.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve