

BELZONA SAVES A BROKEN COMPRESSOR CASING


ID: 5218

Industry: *General Industry*
Application: *ENC-Engines and Casings*
Substrate: *Cast iron*
Products: ** Belzona 1111 (Super Metal) ,*
** Belzona 9341 (Reinforcement Sheet) ,*
** ,*

Customer Location: *Alaska, USA*
Application Date: *1982*

Problem

Freezing water damaged WWII compressor jugs. No replacement available.



Photograph Descriptions

- * Compressor jugs showing broken casting ,
- * Ready for application of Belzona 1111 with studs holding the broken piece in place ,
- * Complete with reinforced Belzona 1111 ,

Application Situation

A broken compressor casing

Application Method

The application was carried out in accordance with Belzona System Leaflet ENC-1. Drilled, tapped and studs to hold the broken piece were put in place. The casing was coated with Belzona 1111, Reinforcement Sheet was embedded, and another coat of Belzona 1111 was applied.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Belzona Facts

This is on a WWII compressor, parts no longer available, the only alternative was a very expensive completely new compressor.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2025