

BELZONA PROTECTS PARAPET WALLS FROM WATER PENETRATION


ID: 5240

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Concrete*
Products: ** Belzona 3911 (PSC Surface Conditioner) ,*
** Belzona 5131 (EG-Cladding) ,*

Customer Location: *Toronto, ON, Canada*
Application Date: *August 2013*

Problem

Water was penetrating the concrete.



Photograph Descriptions

- * Prior to application ,
- * Application in progress ,
- * Completed application ,

Application Situation

Parapet walls of a condominium building.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-10 for sealing leaking areas in parapet walls and copings. A wire brush was used to prepare the surface and brushed off to remove all the dust. Belzona 3911 was applied

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

with a brush to the entire surface. Belzona 5131 was applied with a lambs wool roller in accordance with Belzona Instructions For Use.

Belzona Facts

Belzona 5131 is a coating for long term waterproofing and weatherproofing of exterior and interior walls and structures which provides long term protection. Belzona 5131 also has built-in energy conservation properties providing low thermal conductivity that together with exceptionally low heat capacity, will make cold surfaces feel warm thus minimising condensation and make warm surfaces feel cooler.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

