

BELZONA CREATES IRREGULAR SHIM FOR DRAGLINE ROTATING BLOCK

ID: 5247

Industry: Mining & Quarrying
Application: GSS-Gaskets, Seals and Shims
Substrate: Cast Iron
Products: * Belzona 1341 (Supermetalgilde) ,

Customer Location: BC, Canada
Application Date: 1992

Problem

The base of the rotating block had worn unevenly creating an uneven mounting surface.



Photograph Descriptions

- * View of Dragline Equipment ,
- * Injection ports in place ,
- * Injection gun filled with Belzona 1341 ,
- * Injection in progress ,

Application Situation

Worn rotating block base

Application Method

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-1

Belzona Facts

The use of Belzona 1341 enabled the mine to create an uneven shim between the two metal surfaces saving many hours of downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve