

BELZONA REPAIRS RUBBER TRACK

ID: 5257

Industry: *General Industry*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Washington, USA*
Application Date: *1993*

Substrate: *Rubber*
Products: ** Belzona 2111 (D & A Hi-Build Elastomer),*

Problem

The exposed fabric will wick in water and rot, causing the track to weaken and require replacement.



Photograph Descriptions

- * Caterpillar showing track ,
- * Close up of the cut in the track ,
- * Prepared and conditioned cut ,
- * Completed application ,

Application Situation

The rubber track was cut open, exposing the fabric.

Application Method

The cut on the track was positioned so the cut was open. The rubber was roughened and Belzona 2111 was applied in accordance with Belzona Know-How System Leaflet SHM-15.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

Protecting the fabric has extended the life of the track, saving thousands of dollars and avoiding replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

