

# BELZONA REPAIRS ENGINE CASING

ID: 5260

Industry: *General Industry*  
Application: *ENC-Engines and Casings*  
Substrate: *Cast Iron*  
Products: *\* Belzona 1111 (Super Metal) ,*

Customer Location: *Washington, USA*  
Application Date: *1992*

## Problem

*The engine block had a large piece of the casing broken off.*



## Photograph Descriptions

- \* Engine block showing missing pieces ,
- \* Two pieces locked in place with studs ,
- \* Completed application with Belzona 1111 ,

## Application Situation

Damaged engine casing.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet ENC-1. After the proper surface preparation, the two broken pieces were locked in place using studs and Belzona 1111 was applied.

## Belzona Facts

Twenty dollars worth of Belzona 1111 saved the engine block from being scrapped. The customer was fully satisfied with the results.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve