

BELZONA RESCUES A SNOW PLOW HYDRAULIC PUMP

ID: 5268

Industry: Fluid Flow

Customer Location: Anchorage, Alaska, USA

Application: ENC-Engines and Casings

Application Date: 1983

Substrate: Aluminum

Products: * Belzona 1111 (Super Metal) ,
* Belzona 9341 (Reinforcement Sheet) ,

Problem

The pump had been repaired with brand X, fell apart after five minutes of use.



Photograph Descriptions

- * Aluminum pump casing showing the remains of Brand X failure ,
- * Casing prepared with grinding ,
- * Finished casing ready for service. ,

Application Situation

Broken pump casing

Application Method

The application was carried out in accordance with Belzona System Leaflet ENC-1 using Reinforcement Sheet to bridge the hole.

Belzona Facts

A new pump casing was 5000 miles away and could take two weeks to arrive. Snow does not wait in Alaska.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

www.belzona.com

EMS 695213

Management System.

