

BELZONA IMPROVES SAFETY WITH GRIP SYSTEM ON STEPS

ID: 5273

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: * Belzona 4411 (Granogrip) ,
* Belzona 9221 (Surefoot Aggregate White) ,

Customer Location: Montana, USA

Application Date: 1986

Problem

Stick on strips had caused tripping problems.



Photograph Descriptions

- * Overview of football stadium ,
- * Nosings blasted and masked off ,
- * Brushing on Belzona 4411 ,
- * Completed application, ready for repainting ,

Application Situation

Nonslip on football stadium steps.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The step nosings were blasted. The nosings were masked off and Belzona 4411 was brushed on. Belzona 9221 was sprinkled on.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Stick on strips had proved to be ineffective, causing trip hazards. Belzona 4411 reduced the potential for accidents and provided an aesthetically pleasing finish.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

