

# Belzona Performs a Classic Repair

ID: 529

**Industry:** General Industry  
**Application:** ENC-Engines and Casings  
**Substrate:** Cast Iron  
**Products:** \* Belzona® 1111 (Super Metal) ,  
\* Belzona® 9341 (Reinforcement Tape) ,

**Customer Location:** Motor Enthusiast, Cheshire, England  
**Application Date:** April 2005

## Problem

A small crack had developed in the 2.8 litre engine casing of this 1951 David Brown Lagonda.



## Photograph Descriptions

- \* The engine block ,
- \* The exterior of this fully restored classic car ,
- \* The cars interior ,
- \* The rear view of the car ,

## Application Situation

Engine casing on vintage car

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

## Belzona Facts

Belzona was chosen as being the quickest, simplest and cheapest method of conducting the repair. Other alternatives would have involved welding, which the client did not want to pursue due to the age of the casting. The repair needed to be carried out quickly as the car was to go on show the following day. The total cost was around £15 (\$28) to complete.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve