

# BELZONA SEALS A CRUSHER LUBRICATION TANK

ID: 5294

Industry: *Mining & Quarrying*  
Application: *TCC-Tanks and Chemical Containment Areas*


Customer Location: *Mine, Chile*  
Application Date: *June 2010*

Substrate: *Carbon steel*

Products: *\* Belzona 1111 (Super Metal) ,*  
*\* Belzona 5811 (Immersion Grade) ,*

## Problem

*Oil filtration in the welds and joints. Leaks are detected by applying penetrating dye.*



## Photograph Descriptions

- \* Original tank conditions where the penetration of the dye can be observed ,
- \* Prepared surface ,
- \* Another view of the prepared surface ,
- \* Completed application ,

## Application Situation

Area of welding joints and the entire lower surface of the tank.

## Application Method

Mechanical cleaning with a 4½" angular grinder to create a rough surface. The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

## Belzona Facts

Belzona provided a quick and effective solution carried out in-situ.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve