

BELZONA'S SHAFT REPAIR RESTARTS PRODUCTION

ID: 5313

Industry: *General Industry*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Petrolia, ON, Canada*
Application Date: *August 2012*

Substrate: *Steel*
Products: ** Belzona 1111 (Super Metal) ,*
** Belzona 9411 (Release Agent) ,*

Problem

Shaft was worn and damaged.



Photograph Descriptions

- * Damaged shaft ,
- * Completed preparation ,
- * Application in process ,
- * Completed application ,

Application Situation

Shingle manufacturing machine.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-2 for rebuilding damaged shafts using forming techniques. The area was prepared using a disk grinder to roughen the surface and to make a cross-hatching pattern on the surface. A coat of Belzona 9411 was applied to the inside of the formers, and the edges where material will be pushed out. Belzona 1111 was applied to the shaft and covered the entire area using a brush and the mixing spatula to apply the product. Also, the inside of the formers were covered and evenly spread. The formers were clamped to the shaft. Once Belzona 1111 had cured the former was removed and the excess material was snapped off at the parting lines. Some of the material had flowed onto the shoulder of the shaft, but it was so thin that the area was sanded.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Belzona Facts

Belzona 1111 is a two-component repair composite based on a ceramic steel reinforced polymer system. This fully machinable Belzona product provides a cost effective solution to a wide range of general engineering repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

