BELZONA REPAIRS AND COATS RUBBER SOCK

ID: 5314

Industry: General Industry

Application: SHM-Solids Handling Machinery

Substrate: Rubber

Products: * Belzona 2211 (MP Hi-Build Elastomer),

* Belzona 2221 (MP Fluid Elastomer),

* Belzona 2311 (SR Elastomer),

* Belzona 2911 (Elastomer QD Conditioner),

Problem

The rubber sock was worn.







Customer Location: Richmond Hill, ON, Canada

Application Date: September 2013



Photograph Descriptions

- * Rubber sock,
- * Prior to application,
- * Complete preparation ,
- * Completed application,

Application Situation

Rubber sock that dispenses concrete into the trucks.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9 for creating and repairing rubber linings. The surface was prepared by removing any dirt or debris and cleaned. Belzona 2911 was applied to the prepared area and Belzona 2311 was applied with a brush. Belzona 2211 and Belzona 2221 were applied using a brush in accordance with Belzona Instructions For Use.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



Belzona 2211 and Belzona 2221 are two-component elastomeric polymer repair composites for repairing and rebuilding rubber components. These versatile, high performance elastomers can be applied without the need for specialist tools and will bond strongly to a wide range of substrates including natural rubber, nitrile, neoprene, polyurethane, PVC, steel, copper, aluminum and

