

BELZONA REPAIRS AND COATS RUBBER SOCK

ID: 5314

Industry: *General Industry*

Customer Location: *Richmond Hill, ON, Canada*

Application: *SHM-Solids Handling Machinery*

Application Date: *September 2013*

Substrate: *Rubber*

Products: ** Belzona 2211 (MP Hi-Build Elastomer) ,
* Belzona 2221 (MP Fluid Elastomer) ,
* Belzona 2311 (SR Elastomer) ,
* Belzona 2911 (Elastomer QD Conditioner) ,*

Problem

The rubber sock was worn.



Photograph Descriptions

- * Rubber sock ,
- * Prior to application ,
- * Complete preparation ,
- * Completed application ,

Application Situation

Rubber sock that dispenses concrete into the trucks.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9 for creating and repairing rubber linings. The surface was prepared by removing any dirt or debris and cleaned. Belzona 2911 was applied to the prepared area and Belzona 2311 was applied with a brush. Belzona 2211 and Belzona 2221 were applied using a brush in accordance with Belzona Instructions For Use.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



Belzona 2211 and Belzona 2221 are two-component elastomeric polymer repair composites for repairing and rebuilding rubber components. These versatile, high performance elastomers can be applied without the need for specialist tools and will bond strongly to a wide range of substrates including natural rubber, nitrile, neoprene, polyurethane, PVC, steel, copper, aluminum and concrete.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

