

BELZONA REPAIRS LEAKS IN WATER FEATURE

ID: 5315

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Concrete and steel
Products: * Belzona 3111 (Flexible Membrane) ,
* Belzona 3911 (PSC Surface Conditioner) ,
* Belzona 3921 (GSC Surface Conditioner) ,

Customer Location: Toronto, ON, Canada
Application Date: 1987

Problem
Leaks in the water feature.



Photograph Descriptions

- * Water feature ,
- * Prior to application ,
- * Completed application ,
- * Water feature back online ,

Application Situation

Water feature.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6 for waterproofing gutters and standing water areas. The area was cleaned of any debris and blasted to prepare the surface. Belzona 3911 was applied to the concrete and Belzona 3921 was applied to the steel using a brush. Belzona 3111 was applied to the surface using a brush as a two coat system.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Belzona Facts

Belzona 3111 is a single component, solvent free, microporous coating for the long-term repair and protection of all types of roofs. This versatile liquid applied material provides outstanding weatherproofing and waterproofing properties with excellent protection against infrared and ultra violet radiation and provides long-term protection for 20 years plus.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

