

BELZONA PROTECTS STERN TUBE

ID: 5353


Industry: Marine
Application: SOS-Ships and Offshore Structures

Customer Location: Oregon, USA
Application Date: 2014

Substrate: Steel
Products: * Belzona 5811 (Immersion Grade),

Problem

The US Army required standard protection against erosion and corrosion when the ship is dry docked.



Photograph Descriptions

- * Stern of the ship ,
- * Inspecting the grit blast ,
- * First coat of black Belzona 5811 ,
- * Second coat of gray Belzona 5811 ,

Application Situation

Stern tube in a US Army Ship.

Application Method

The stern tube was grit blasted and then two coats of Belzona 5811 were brushed on. The application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Belzona lasts through the expected time between inspections by the US Army.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

