

BELZONA REPAIRS STEERING GEAR

ID: 536

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Cargo Ship - Egypt*
Application Date: *December 2003*

Substrate: *Steel.*
Products: ** Belzona® 1111 (Super-Metal) ,*
** Belzona® 1121 (Super XL-Metal) ,*
** Belzona® 9411 (Release Agent) ,*

Problem

Severe corrosion on the affected areas of the rudder stock and pintle housing areas.



Photograph Descriptions

- * General view of the cargo ship. ,
- * Rudder stock being machined back to its dimensions after repair. ,
- * Belzona® 1121 was applied to both pintle and pintle housing. ,
- * Rudder being installed. ,

Application Situation

Rudder stock - upper housing and pintle housing.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets SOS-3 and MPT-1.

Belzona Facts

Belzona easily performed the work in-place with minimum repair time. The excellent corrosion resistance of Belzona® 1111 and Belzona® 1121 made them the ideal choice for long-term protection in these areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve