# BELZONA EXTENDS THE LIFE OF HYDRAULIC RAMS

ID: 5364

Industry: Pulp & Paper Customer Location: WA, USA
Application: MPT-Mechanical Power Transmission Application Date: 1985

Substrate: Steel

Products: \* Belzona 1111 (Super Metal),

#### Problem

Three hydraulic rams had been scored and the loss of oil was so bad that they had built a dam so the oil would drain into a 55 gallon drum. At the end of each shift the oil was pumped back into the reservoir. They had tried repairing the score with another material, but it fell off after one pass.







# **Photograph Descriptions**

- \* Plywood press showing damaged hydraulic rams,
- \* Rams repaired,
- \* Close up of one repaired ram,

#### **Application Situation**

Plywood press with scored hydraulic rams.

### **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-3. The damaged area was so large that a straight edge could not be used. We ground a shoulder following the damage, drilling the corners to keep the edges square.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

# **Belzona Facts**

Fabricating new rams was so expensive that they were searching for a used plywood press to replace the unit. Still, the cost would be thousands of dollars. Less than \$100.00 of Belzona 1111 along with a half a day's labor saved the plywood press. Thirty years later, the plywood press with the repaired rams is still operating.

www.belzona.com