

BELZONA STOPS LUBE LEAKS

ID: 5373

Industry: Oil & Gas
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 5811 (Immersion Grade) ,
* Belzona 9331 (Reinforcing sheet) ,

Customer Location: Beaumont, Texas, USA
Application Date: April 2014

Problem

The customer stored lube oil within a small containment area, when leaks would develop they would by-pass and go under the wall onto the ground outside of the containment area.



Photograph Descriptions

- * Before repair ,
- * During repair ,
- * Application completed ,

Application Situation

Concrete wall leaking lube oil

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-3.

Belzona Facts

The customer was using vital manpower and resources having to constantly clean-up the ground outside of the containment area,

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



the Belzona application keeps the lube within the containment for easy clean-up.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

