

# BELZONA REPAIRS A VACUUM PUMP


ID: 5375

Industry: Fluid Flow  
Application: CEP-Centrifugal Pumps  
Substrate: Steel  
Products: \* Belzona 1311 (Ceramic R-Metal) ,  
\* Belzona 9341 (Reinforcement Tape) ,

Customer Location: British Columbia, CA  
Application Date: August 2014

## Problem

The outlet port had corroded to the point a hole had formed; a competitor's patch product had been applied but failed after a short time.



## Photograph Descriptions

- \* 1. Image of the leak ,
- \* 2. The surface preparation requires a number of tools due to the tight space ,
- \* 3. Exposed hole is a bit larger than expected ,
- \* 4. The application complete ,

## Application Situation

This vacuum pump handles mildly acidic filtrate.

## Application Method

The application was carried out in accordance with the Belzona Know-How System Leaflet CEP-6.

## Belzona Facts

This facility has a long history of successful Belzona repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve