

Belzona repairs crude oil leaks

ID: 5376

Industry: Oil & Gas
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon Steel
Products: * Belzona 1221 (Super E-Metal) ,
* Belzona 1161 (Super UW-Metal) ,

Customer Location: Houston, Texas, USA
Application Date: November 2013

Problem

After testing a newly installed line, the customer found a pinhole leak at a weld. Hot work was not permitted because crude oil was now in the line.



Photograph Descriptions

- * Cleaning of the immediate area ,
- * Belzona 1221 was used to stop leak ,
- * Belzona 1161 used to encapsulate for long term protection ,

Application Situation

Pinhole leak at weld on a crude oil line.

Application Method

The application was carried out using a modified version of Belzona Know-How System Leaflet VPF-11. Belzona 1221 was used to stop the immediate leak. The area surrounding the leak was then prepared and Belzona 1161 was applied for long term protection.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

To purge the line in order to weld would have taken days and thousands of dollars, the Belzona repair was made in less than an hour and the customer was up and running the same day.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

