

BELZONA IMPROVES WORKING CONDITIONS BY SEALING THE ROOF OF A CHOCOLATE FACTORY

ID: 5398

Industry: *Food & Drink*

Customer Location: *MO, USA*

Application: *RPA-Roof Problem Areas*

Application Date: *March, 2008*

Substrate: *Rubber*

Products: ** Belzona 3111 (Flexible Membrane) ,*

** Belzona 4111 (Magma-Quartz) ,*

Problem

Minor leaks were causing unsanitary conditions in the kitchen and the HVAC system could not keep up with the major temperature and humidity fluctuations causing discoloration in the highly decorative chocolates.



Photograph Descriptions

- * Storefront image ,
- * The roof prepared and ready for application ,
- * Picture of the first 1/2 of sprayed Belzona 3111 ,
- * Picture of finished installation of Belzona 3111, including repaired parapets ,

Application Situation

Poorly insulated roof

Application Method

The roof was pressure washed and the parapets were re-pointed with Belzona 4111. The roof was then completely sealed and protected with the Belzona 3111 system. The application was carried out in accordance with a modified version of Belzona System Leaflet RPA-10.

Belzona Facts

The owner remarked about the noticeable difference in temperature and humidity control after just the first coat of Belzona 3111

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



was applied.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

