

BELZONA REPAIRS AND PROTECTS PUMP CASING

ID: 5415

Industry: General Industry
Application: CEP-Centrifugal Pumps
Substrate: Cast Iron
Products: * Belzona 1111 (Super Metal) ,
* Belzona 1341 (Supermetalglide) ,

Customer Location: BC, Canada
Application Date: July 2002

Problem

Pump casing was showing signs of degradation. This was from possible contamination during casting process.



Photograph Descriptions

- * View of casing showing damaged areas requiring rebuilding. ,
- * Application of 1st coat of Belzona 1341 in progress ,
- * Completed application. ,

Application Situation

Pump Casing

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-3, CEP-5.

Belzona Facts

A Belzona repair allowed the damaged areas to be quickly rebuilt and the casing protected from further bi-metallic erosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve