

BELZONA REMEDIATES A DOCK AT A SUGAR REFINERY

ID: 5428

Industry: Sugar
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 4911 (Magma TX Conditioner) ,
* Belzona 9111 (Cleaner/Degreaser) ,

Customer Location: South Louisiana, USA
Application Date: August and September 2014

Problem

Abuse from the metal tractor wheels combined with sugar and water causing concrete to be eroded. The dock was becoming unsafe for equipment and pedestrians.



Photograph Descriptions

- * 1. Before the application in the first area ,
- * 2. Application complete in the first area ,
- * 3. Before the application in the second area ,
- * 4. Application complete in the second area ,

Application Situation

Concrete Dock at a Sugar Refinery

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

Safety issues are being resolved. Belzona product is the first polymer repair product the Customer has used that didn't fail in the first few days of operation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve