

BELZONA REPAIRS A DOCK HOSE BEFORE INSPECTION

ID: 5431



Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Terminal Dock, Louisiana, USA*
Application Date: *July 2013*

Substrate: *Rubber*
Products: ** Belzona 2311 (SR Elastomer) ,*
** Belzona 2911 (Conditioner) ,*

Problem

Over the years as the dock hose had been drug around the deck and over shipside, the hose had been cut and gouged.



Photograph Descriptions

- * 1. Area being prepared for repair. ,
- * 2. Area after Belzona 2911 applied. ,
- * 3. Belzona 2311 applied. ,
- * 4. Finished repair before tape removed. ,

Application Situation

Rubber Dock Hose with cuts.

Application Method

After proper surface preparation, the application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

Belzona Facts

Customer spent less than \$50.00 to repair cosmetic cut in hose for Coast Guard approval to keep using the hose versus spending \$2,500 or more for a new hose.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve