

# BELZONA REBUILDS AND PROTECTS RUDDERS

ID: 5442

Industry: *Marine*

Application: *SOS-Ships and Offshore Structures*

Customer Location: *BC, Canada*


Application Date: *December 2004*

Substrate: *Mild steel*

Products: *\* Belzona 1311 (Ceramic R Metal) Belzona 1341 (Supermetalgilde) ,*

## Problem

*Vessel rudders are subjected to continuous erosion and cavitation attack.*



## Photograph Descriptions

- \* 1. Rudders in set up after blasting ready for application. 2. Rudders after application of 2 coats of Belzona 1341 Supermetalgilde. 3. Condition of rudders / rudder horn after 12 years of service with Belzona coating. ,

## Application Situation

Rudder

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SOS-1/2

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve