

Belzona Repairs Ships Generator Shaft

ID: 546


Industry: *Marine*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Shipping company - Egypt*
Application Date: *February 2005*

Substrate: *Steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Worn generator drive shaft located in a narrow, confined place.



Photograph Descriptions

- * View of the generator shaft prior to the repair. ,
- * Surface preparation in progress. ,
- * Form was applied. Then excess material was removed. ,
- * Completed shaft repair. ,

Application Situation

Generator drive shaft of a transport ship.

Application Method

Application was carried out in accordance with Belzona® Know-How System Leaflet MPT-2.

Belzona Facts

Belzona successfully repaired the shaft in a cramped environment without disassembling the shaft. This allowed the ship to keep schedule without delay.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve