

# BELZONA REPAIRS AND PROTECTS BULB GENERATOR SET


ID: 5472

Industry: Power  
Application: ENC-Engines and Casings  
Substrate: Steel and Stainless steel  
Products: \* Belzona 1111 (Super Metal) ,  
\* Belzona 1341 (Supermetalglide) ,

Customer Location: Hydropower Plant - France  
Application Date: March 2001

## Problem

Important infiltration and corrosion between stainless steel jacket and turbine housing.



## Photograph Descriptions

- \* General view of the housing ,
- \* Junction between steel and stainless steel ,
- \* Completed repair and protection ,

## Application Situation

Bulb generator set.

## Application Method

The damaged junction was repaired with Belzona 1111 and protected with Belzona 1341. The application was completed by the customer.

## Belzona Facts

Quick, on-site and cold repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve