

BELZONA PROTECTS CYCLONE



ID: 5473

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona 1311 (Ceramic R-Metal) ,
* Belzona 1321 (Ceramic S-Metal) ,

Customer Location: France
Application Date: August 2004

Problem

Abrasion inside the cyclone and through-wall damages caused by corncobs.



Photograph Descriptions

- * Cyclone to be repaired ,
- * Presence of holes due to abrasion ,
- * Repair with Belzona 1311 and protection with Belzona 1321 ,

Application Situation

Inside a cyclone transporting corncobs in a cereal plant.

Application Method

The application was carried out with cold bonding of stainless steel plates with Belzona 1311, where abrasion protection was important. Belzona 1321 was applied to protect 15cm of all the circumference of the cyclone.

Belzona Facts

Belzona offered a quick repair and rapid return to service. The repair was completed on-site, without dismantling. Belzona allowed for a cold repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Copyright © Belzona International Limited 2024