

# BELZONA MAKES FOR BETTER SHOPPING

ID: 5477

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 4111 (Magma-Quartz) ,

Customer Location: Spokane, WA, USA  
Application Date: September 2014

## Problem

Concrete floor has broken out near a relief cut. With heavy forklift traffic during overnight stocking causing the damage, it is unsafe for pedestrian traffic during business hours. Previous patch material has been used but it breaks out soon after application, causing even more damage to the concrete.



## Photograph Descriptions

- \* Prior damage and patch. Patch removed. ,
- \* Starting the application using the mixing board formers. ,
- \* Finishing the application with the formers. After removing the formers. ,
- \* One month later. Still looking brand new. ,

## Application Situation

Damaged concrete at a wholesale shopping store.

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-5 using 1" strips of a Belzona mixing board as the former to maintain the relief cut.

## Belzona Facts

Existing patch materials needed to be reapplied a couple of times per year. When the existing patch material was removed, it came loose in large pieces, thus showing it had not bonded to the concrete substrate and still had a very strong chemical odor even after being applied months before. Upon opening and mixing Belzona 4111 for the repair, the customer remarked that there was no odor coming from the Belzona product. This customer is happy that they have a long-lasting solution that is easy for them to use. They will save money of repeat maintenance to the same damage.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

