

BELZONA PROVIDES NON-SLIP SURFACE AT SCHOOL ENTRANCE.

ID: 5499

Industry:

Application: FPA-Floor Problem Areas

Substrate: Concrete


Products: * Belzona 4411 (Granogrip) ,
* Belzona 9221 (Surefoot Aggregate White) ,

Customer Location: School, Derbyshire

Application Date: August 2014

Problem

Steps presented a slip hazard to pupils, staff and visitors when entering and exiting the school.



Photograph Descriptions

* 1. Damaged Steps 2. Damaged steps- close up 3. Completed Application 4. Completed Application - close up ,

Application Situation

Worn Steps

Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8. Belzona 9221 was encapsulated in the Belzona 4411 and applied in an even coat.

Belzona Facts

The school had used Belzona 4411 in the past and were pleased with the results and therefore chose Belzona again for this application. The entire application was completed in one day. The Belzona 4411 yellow provides a visual guide to the step nosings as well as a hard wearing non-slip surface.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve