### BELZONA PROTECTS PIPE WITH INTERNAL LINING

ID: 5524

Industry: Oil & Gas Customer Location: Oil and Gas Company, BA, Brazil

Application: VPF-Valves, Pipes and Fittings Application Date: July 2009

Substrate: Carbon Steel

Products: \* Belzona 1121 (Super XL-Metal),

\* Belzona 5891 (HT Immersion Grade),

#### **Problem**

Since the operating fluid (produced water) is very corrosive, these pipes needed the internal protection in order to increase its working life.









# **Photograph Descriptions**

- \* Internal surface after blasting.,
- \* Internal surface of the pipe coated with Belzona 5891.,
- \* Close-up after the application of Belzona 5891.,
- \* Overview of the pipelines.,

### **Application Situation**

New pipes without an internal coating need protection to be put into operation.

### **Application Method**

The weld seams and irregularities were roughened by grinding. The internal surface of the pipes was prepared by blast cleaning to a near white metal finish, SSPC SP-10 Sa 2½ standard. After the removal of residue and cleaning with a degreaser, Belzona 1121 was applied to smooth the weld seams/irregularities. Then the 1st layer of Belzona 5891 was applied at a thickness of 300-400 microns. After the initial mechanical stability of Belzona 5891, brush-off blast cleaning was carried out and the 2nd layer of Belzona 5891 was applied at a thickness of 300-400 microns. In the straight sections, the coating of Belzona 5891 was applied. Inspection was carried out and the identified misses were retouched.

# **Belzona Facts**

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



ation.			