# **Belzona Protects Fans From Abrasion**

ID: 554

Industry: General Industry Customer Location: Tobacco company, Egypt

Application: FBC-Fans, Blowers and Compressors Application Date: February 2002

Substrate: Steel

Products: \* Belzona® 1812 (Ceramic Carbide FP),

**Problem** 

The fans need to be protected from strong abrasion of tobacco which has worn the fans out in only three months.









## **Photograph Descriptions**

- \* General view of tobacco suction fans,
- \* Fans following surface preparation,
- \* Fans coated with Belzona® 1812 (Ceramic Carbide FP),
- \* Five fans were protected,

## **Application Situation**

Suction fans

### **Application Method**

Application was carried out in accordance with Belzona Know-How System Leaflet FBC-2.

### **Belzona Facts**

The tobacco suction fans were worn out and replaced every three months. After coating the fans with Belzona® 1812 the fans provided over a year of service before they are touched up. Other fans in the tobacco facility are coated regularly.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve