BELZONA OFFERS ANTICORROSIVE AND PEELABLE PROTECTION FOR FLANGES

ID: 5565

Industry: Oil & Gas Customer Location: Bahia, Brazil

Application: GSS-Gaskets, Seals and Shims Application Date: January and February, 2015

Substrate: Carbon Steel

Products: * Belzona 3411 (Encapsulating Membrane),

* Belzona 8411,

* Belzona 9311 (Reinforcing Sheet),

Problem

The complex geometry of the flanged joints facilitates the occurrence of problems, such as crevice corrosion in the void between the two flange faces and galvanic corrosion, where the use of different metals can create serious consequences.









Photograph Descriptions

- * Corroded flange,
- * Application of Belzona 8411,
- * Application of the second coat of Belzona 3411 (Grey) over the first coat (Beige),
- * Completed application,

Application Situation

Flanged joints connecting the pipework

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-11. The surface preparation was carried out manually with emery cloth according to the standard SSPC SP2/SP3, equivalent to St2/St3. After the surface was prepared and cleaned, the joints were sealed between the flange faces with tape and Belzona 8411, a corrosion inhibitor, was applied. After the protection of bolts with caps, Belzona 3411 was applied in two coats, utilizing Belzona 9311 in the circumference and in the

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

extremities of the flanges. At the end, a visual inspection was carried out.

Belzona Facts

The client was very satisfied with the simple application of Belzona 3411, which offers excellent corrosion resistance and allows for eassy access to flange fastenings with its peelable and resealable system.

www.belzona.com