

BELZONA REPAIRS TURBINE WICKET GATES

ID: 5599

Industry: Power
Application: CEP-Centrifugal Pumps
Substrate: Steel
Products: * Belzona 1221 (Super E-Metal) ,
* Belzona 1341 (Supermetalgilde) ,

Customer Location: Hydropower Plant, USA
Application Date: 1998

Problem

The wicket gates were suffering from cavitation damage due to the water flow. This unit has 1,000,000 gallons of water per minute running through it.



Photograph Descriptions

- * Cavitation damage to the wicket gate ,
- * Close up of the repaired area with no more cavitation ,
- * Completed application ,

Application Situation

Wicket gates

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-5.

Belzona Facts

The hydropower plant saved time and money by repairing the wicket gates in situ instead of removing them from the plant to be repaired.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve