

No Job is Too Small for Belzona

ID: 565

Industry: *Transport*

Customer Location: *Motocross enthusiast - Northern Italy
(Piacenza)*

Application: *ENC-Engines and Casings*

Application Date: *January 2005*

Substrate: *Aluminium casting*

Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Activities during a motocross race caused a stripped thread. Piece of equipment quite expensive.



Photograph Descriptions

- * Yamaha YZ 250 ,
- * Broken thread ,
- * Completed work ,
- * See the rebuilt fillet ,

Application Situation

Yamaha YZ 250 cc - 2001

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-2. The area was post-cured at 50° C for five hours to ensure that the oil seals were not damaged.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Still in service after months of intensive use.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

