

# No Job is Too Small for Belzona

ID: 565

Industry: *Transport*

Customer Location: *Motocross enthusiast - Northern Italy  
(Piacenza)*

Application: *ENC-Engines and Casings*


Application Date: *January 2005*

Substrate: *Aluminium casting*

Products: *\* Belzona® 1111 (Super Metal) ,*

## Problem

*Activities during a motocross race caused a stripped thread. Piece of equipment quite expensive.*



## Photograph Descriptions

- \* Yamaha YZ 250 ,
- \* Broken thread ,
- \* Completed work ,
- \* See the rebuilt fillet ,

## Application Situation

Yamaha YZ 250 cc - 2001

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-2. The area was post-cured at 50° C for five hours to ensure that the oil seals were not damaged.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Still in service after months of intensive use.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

