

BELZONA STOPS THE LEAKS ON HVAC TUBES


ID: 57

Industry: *Chemical & Petrochemical*
Application: *VPF-Valves, Pipes and Fittings*
Substrate: *Copper*
Products: ** Belzona®1111 (Super Metal) ,*

Customer Location: *Petrochemical Plant in Texas, U.S.A.*
Application Date: *1991*

Problem

Leaking coolant



Photograph Descriptions

- * An area was cut to gain access to the leaking pipe ,
- * Leak stopped with Belzona® 1111 (Super Metal) ,

Application Situation

Tube in HVAC coil

Application Method

Application was carried out in accordance with Belzona Know-How Leaflet VPF-11a.

Belzona Facts

After six years the repair is still in place.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve